

HayTemp 1700

Hay temperature measuring instrument

GENERAL:

Since stored hay or straw, etc., tends to overheat (causing depreciation) or even self-ignite due to biological processes, especially at higher material moisture, regular temperature control in the feed bunk is important. The HayTemp 1700 optimally supports both farmers and fire departments

For measurements in hay and straw at a depth of up to 4 m.

TECHNICAL SPECIFICATIONS:

Device: G 1700 Measuring range: -20..+120 °C Probe connection: BNC, Pt1000, 2-wire Measuring rod: Fiberglass probe, approx. 4 m long, Ø approx. 10 mm, 1 measuring point in the probe tip

Cutting tip: screwable double-edged tip with integrated

Measuring rod with cutting tip approx. 600 g. Weight: Scope of delivery: Display device, fiberglass tube, Pt 1000 probe tip, BNC cable (1.5 m), battery, operating instructions

ACCESSORIES OR SPARE PARTS:

G 1700

Item No. 609826

Waterproof alarm thermometer for BNC interchangeable sensors

Fiberglass tube

4 m, without probe and without tip

Probe tip

Item No. 606889

with integrated temperature sensor

Cable BNC/BNC


Connection cable with a length of 1.5 m

ST-G1000

Protective bag, leather, G 1000 protective bag made of Nappa leather, a universal cutout for

Measuring devices for hay and straw humidity see BaleCheck

SOIL THERMOMETER



SoilTemp 1700

Item No. 611374

Robust soil & compost thermometer

GENERAL:

The universal display device, combined with an extremely robust and at the same time ergonomic T-handle probe made of stainless steel, enables many measurements in floors and bulk goods.

APPLICATION:

Feedstock control, measurements in soils, landfills, silage, compost and much more.

TECHNICAL SPECIFICATIONS:

Device: G 1700 Probe connection: BNC, Pt1000, 2-wire Measuring range: -50.0 .. + 250.0 °C Measuring lance: Stainless steel, 1000 mm x Ø 10 mm, 1 m; connection cable with BNC plug, 350 g, feeler handle construction enables fatigue-free work.

Scope of delivery: Display device, GTF 40 T-1000, battery, operating instructions

ACCESSORIES OR SPARE PARTS:

G 1700

Item No. 609826

Waterproof alarm thermometer for BNC interchangeable sensors

GTF 40 T-620

Stainless steel T-handle insertion probe, FL 620 mm, with 1 m cable and BNC connector

GTF 40 T-1000 Item No. 60679

Stainless steel T-handle penetration probe, FL 1000 mm, with 1 m cable and BNC connector

GTF 40 T-1500

Stainless steel T-handle insertion probe, FL 1500 mm, with 1 m cable and BNC connector

ST-G1000

Protective bag, leather, G 1000 protective bag made of Nappa leather, a universal recess for sensors, belt clip