

Sensor shelter TS (Traverse System)

Ident-No.:
00.08141.610000

Sensor shelter for direct
installation at traverse system
14627

consisting of:
1 Holding fixture with 30 mm-bore
2 Screws M 8 x 16 DIN 933
2 Lock washer 8.4
2 Slot nuts M8

Required tools


- Box wrench/open-end spanner or box spanner
 - SW13 Nut, hexagon head screw

Eventually further tools for the mounting of the sensors will be needed. For more information please have a look at the operating instructions of the appropriate sensors.




Because the installation takes place in a dangerous height, the assembly personal must follow the rules for prevention of accidents.


Mounting of the sensor shelter TS at the traverse profile



When inserting the slot nuts care must be taken to arrange the M8 threaded holes by pairs in line with the end of the traverse.



Mounting of the sensor shelter TS at the mast fixation



Quality System certified by DQS according to
DIN EN ISO 9001:2008 Reg. No. 003748 QM08

Subject to change without notice.

09.14